| |

Hilcorp Alaska, LLC

Post Office Box 244027 Anchorage, AK 99524-4027

3800 Centerpoint Drive Suite 1400 Anchorage, AK 99503

Phone: 907/777-8300 Fax: 907/777-8301

May 3, 2017

Geoff Merrell
State On-Scene Coordinator
Alaska Department of Environmental Conservation
555 Cordova Street
Anchorage, AK 99501

Re: Middle Ground Shoal Platform, Natural Gas Pipeline Release

Middle Ground Shoal Gas Leak Sampling and Monitoring Plan Summary Report

Sampling Period #7 ending 05/02/2017

Dear Mr. Merrell:

Hilcorp Alaska, LLC ("Hilcorp") submitted the Middle Ground Shoal Gas Leak Sampling and Monitoring Plan ("Plan") to the Department of Environmental Conservation ("Department") on March 8, 2017. Preliminary approval to implement the Plan was provided by the Department on March 10, 2017. As described in Section 3.2 of the Plan, Hilcorp is submitting this seventh weekly summary report to the Department.

In an effort to provide data to the Department as quickly as possible, a complete and thorough quality control evaluation has not been completed at this time. Please note that all data presented in this report is preliminary and should be considered as such until a quality control evaluation is completed. Hilcorp will continue to evaluate data quality and will notify the Department of any significant issues as soon as possible.

Ice Monitoring:

Hilcorp regularly monitored ice conditions in the area of the gas leak using helicopter overflights and platform observations as conditions allowed. Observations were compared to the National Oceanic and Atmospheric Administration (NOAA) ice forecasts and provided to the Department via Situation Reports.

On April 17, 2017, Hilcorp submitted an Amendment to the Department to stop daily ice monitoring efforts due to warmer temperatures. The Amendment was accepted by the Department on April 18, 2017. Ice monitoring activities described in the Plan are considered complete.

Fish and Wildlife Monitoring:

On April 26, April 28, and May 1, one Cook Inlet Spill Prevention & Response, Inc. (CISPRI) protected species observer and one wildlife observer professional from International Bird Rescue conducted extended overflights of approximately 20 square miles surrounding the gas leak location (within a 5-mile

diameter circle). The helicopter was able to fly at approximately 300-400 feet altitude. To avoid incidental harassment of marine mammals, altitude would have been increased to 1500 feet, but only in the case where marine mammals were spotted near the helicopter. Flight circles were approximately 0.5 miles apart. Flight conditions and visibility were good during all flights. Various bird species were observed within the 20 square mile area and marine mammals were observed outside the 20 square mile area.

Wildlife observer reports are provided in Attachment A. The last fish and wildlife monitoring event is scheduled for today (5/3), conditions permitting. Observer reports from the last monitoring effort will be submitted to the Department as part of the final weekly summary report on May 10, 2016.

Water Quality Sampling:

The water quality buoy was successfully deployed three times on April 25, 2017. The buoy was equipped with sensors to monitor temperature, pH, salinity, ORP, conductivity, relative conductivity, and concentrations of dissolved oxygen and methane. During Sampling Period #7, the buoy was tethered to the deck to allow for periodic adjustment of the buoy's travel path. This method of deployment reduced the depth of the instruments in the water column to 1, 6.5, and 11.5 meters below the water surface.

Drifts passed between 27.9 and 202 meters from the gas release site. Water quality sampling during Sampling Period #7 showed limited variability in dissolved oxygen, methane, and carbon dioxide concentrations. The lowest dissolved oxygen reading observed (11.55 mg/L) was well above the water quality standard specified under 18 AAC 70 for marine waters. The highest methane concentration observed was 0.107 mg/L at 6 meters below the water surface. No violations of state water quality standards were identified.

Three four-gas meters were used to monitor air conditions continuously to establish a safe work zone during all vessel-based sampling efforts. Lower Explosive Limit (LEL) readings from the meters did not exceed 0%.

A summary report and additional safety documentation for the water quality sampling efforts are provided in Attachment B. The final weekly water quality sampling effort occurred yesterday (5/2). Data is currently being downloaded and evaluated and will be submitted to the Department as part of the final weekly summary report on May 10, 2016. Field activities associated with water quality sampling described in the Plan are considered complete.

Air/Water Interface Sampling:

The final monthly air/water interface sampling effort occurred yesterday (5/2). Data is currently being downloaded and evaluated and will be submitted to the Department as part of the final weekly summary report on May 10, 2016. Field activities associated with air/water interface sampling described in the Plan are considered complete.

Acoustic Monitoring:

Acoustic monitoring described in the Plan was conducted previously on Sunday March, 27, 2017. A second acoustic monitoring effort using Autonomous Multichannel Acoustic Recorders (AMARs) was

Geoff Merrell May 3, 2017 Page 3 of 3

conducted between April 7, 2017 and April 22, 2017. On April 17, 2017, Hilcorp submitted an Amendment to the Department to submit this additional acoustic monitoring data as part of the Plan. The Amendment was accepted by the Department on April 18, 2017. Field activities associated with acoustic monitoring described in the Plan are considered complete. Acoustic data is currently being evaluated and will be submitted to the Department as soon as it is available.

If you have any questions or concerns regarding this letter, please feel free to contact either myself or the appropriate Hilcorp staff member as we continue to work with you on our ongoing response to this event.

Sincerely,

William G. Britt, Jr. Environmental Manager

Attachments:

Attachment A: Fish and Wildlife Monitoring Summary Reports

Attachment B: Water Quality Sampling Summary Report

ATTACHMENT A FISH AND WILDLIFE MONITORING SUMMARY REPORT

April 26, 2017 Report Hilcorp Cook Inlet Wildlife Surveys By Wildlife Observer, Responder, IBR

I arrived at Ross Aviation at 6:30 am, and took Hilcorp charter from Anchorage to Kenai, landing in Kenai about 7:00 am. I confirmed my return flight with Hilcorp logistics, and picked up a Hilcorp pool car at the Kenai hangar. Weather was cloudy with sprinkles, with no ice in the inlet.

I ate breakfast, and checked for any recent relevant bird sightings in the upper Cook Inlet area from eBird.org (see below) and the AK Birding listserv (none). Spring migration is well underway

From eBird.org:

Location Anchor Point--Anchor River Mouth, Kenai Peninsula County, Alaska, US

Sun Apr 23, 2017 2:15 PM

Duration:

2 hour(s)

Observers:

Wildlife Observer

Marine Bird Species Seen:

X Surf Scoter

X White-winged Scoter

X Black Scoter

X Common Loon

X Bald Eagle

X Black-legged Kittiwake

X Herring Gull

X Glaucous-winged Gull

X Glaucous Gull

I visited CISPRI briefly during their spill drill, then arrived at OSK helipad about 10 am with PSO, from CISPRI. We arrived earlier than scheduled due to logistical coordinator's request. We conducted the wildlife survey from 10:34-11:34 am during outgoing tide (slack tide was predicted at 11:42 am). There was no ice in the survey area, and the seas were calm with good visibility (see photo).

I sat on the outside circling window as we made clockwise circles around the leak site. The outer ending GPS point (west side) was 60° 52.1954 N, 151°24.8575 W (taken by CISPRI PSO

who mentioned that these were a different coordinate system--?). I saw 1 gull near the dock, 1 gull sitting on a gravel island in the middle of the inlet, 2 large light-colored shorebirds (?) that flushed off some floating debris, and a raven flying past the helicopter. The pilots remarked on seeing some birds, but they were not identified. CISPRI PSO did not report any additional birds seen from the inside circling window.

I visited the Kenai River mouth area about 1 pm during low tide, and observed hundreds of gulls and a few Bald Eagles near the coast. I also made a stop at the Kenai Flats wildlife observation platform but no other species of marine birds were spotted.

I departed Kenai at 5 pm on the Twin Otter, and arrived at Ross Aviation hangar in Anchorage about 5:30 pm.

April 28, 2017 Report
Hilcorp Cook Inlet Wildlife Surveys
By Wildlife Observer, Responder, IBR

I arrived at Ross Aviation at 6:30 am, and took Hilcorp charter from Anchorage to Kenai, landing in Kenai about 7:00 am. I confirmed my return flight with Hilcorp logistics, and picked up a Hilcorp pool car at the Kenai hangar. Weather was partly cloudy, with no ice in the inlet.

I ate breakfast, and checked for any updated relevant bird sightings in the upper Cook Inlet area from eBird.org and the AK Birding listserv (none). Spring migration is well underway.

I visited the Kenai River mouth about 9 am during outgoing tide, and saw hundreds of gulls and three bald eagles, but no other marine birds.

I worked at the CISPRI office to check website data and to draft reports. I arrived at OSK helipad about 12 noon with CISPRI PSO. Due to logistical request, we conducted the wildlife survey from 12:45-1:45 pm. Slack tide was predicted at 1:10 pm but actually started at 1:35 pm. There was no ice in the survey area, and the seas were calm with good visibility (see photo).

I sat on the outside circling window as we made clockwise circles around the leak site. The outer ending GPS point (west side) was 60°48.7129N, 151°34.7360W (taken by CISPRI PSO). I saw a flock of tan shorebirds (about 20) flying over the water about ½ mile south of the A Platform, and 1 gull flying over west over a gravel bar in the center of the inlet. CISPRI PSO observed additional birds seen from the inside circling window, including 1 gull flying east, 2 black and white birds flying SE (possibly White-winged Scoters after he saw them in bird field guide), 1 white and gray gull-type bird hovering over a gravel bar (likely Arctic Tern), and 1 adult Bald Eagle.

Hilcorp logistics coordinator at OSK helipad, reported that a colleague had seen a pod (about 7) belugas near the OSK dock on April 26 in the afternoon.

I departed Kenai at 4:30 pm on the Twin Otter, and arrived at Ross Aviation hangar in Anchorage about 5 pm.

May 1, 2017 Report
Hilcorp Cook Inlet Wildlife Surveys
By Wildlife Observer, Responder, IBR

I arrived at Ross Aviation at 6:30 am, and took Hilcorp charter from Anchorage to Kenai, landing in Kenai about 7:00 am. I confirmed my return flight with Hilcorp logistics, and picked up a Hilcorp pool car at the Kenai hangar. Weather was mostly cloudy, with no ice in the inlet.

I ate breakfast, and checked for any updated marine bird sightings in the upper Cook Inlet area from eBird.org (see below) and the AK Birding listserv (none). Spring migration is well underway.

From eBird.org:

April 28, 2017 Kasilof River mouth -observed by Wildlife Observer

4 Surf Scoters

1 White-winged Scoter

7 Bald Eagles

30 Mew Gulls

400 Herring Gulls

10 Glaucous-winged Gulls

1 Common Loon

(also various other waterbirds, shorebirds, and songbirds)

April 25, 2017 Erik Hansen Scout Park, Kenai - observed by Wildlife Observer 5 Bald Eagles

20 Mew Gulls

I walked the beach on the north side of the Kenai River mouth from 10:15-11am during outgoing tide, and saw 3 Bald Eagles, 4 Mew Gulls, 10 Herring Gulls, and hundreds of other unidentified gulls at a distance, but no other marine birds. I also saw a pod of beluga whales (6-8 individuals) swimming out of river mouth, and a minke whale with them (identified by color, size, small dorsal fin, visible flukes when diving, and grooves on back).

I worked at the CISPRI office to draft reports. I arrived at OSK helipad about 2:30 pm with CISPRI PSO.

We began the survey at 3:30 pm. Predicted slack tide was 3:37 pm, but at Platform C it was closer to 4 pm. There was no ice in the survey area, and the seas were fairly calm with good visibility (see photo). I sat on the outside circling window as we made clockwise circles around

the leak site. The outer ending GPS point (west side) was very close to last survey (60°48.7129N, and 151°34.7360W) although we were not able to take an exact reading. I saw 5 unidentified gulls in 3 different groups in the survey area. CISPRI PSO did not see any birds from the inside circling window.

I departed Kenai at 6 pm	on the Twin Otter,	, and arrived at Ro	oss Aviation hangar	in Anchorage
about 6:30 pm.				

	Date	1	Start	End	Slack	Tide	Approx	Approx	Approx	%	Beaufort	Swell	Nikiski	Air	Wind	_	Visib	Cloud	Precip	Pilot	Marine	Comments
		Obs	Time	Time	Tide Time	Loc	Survey Speed	Survey Alt (ft)	Area Obs	Open Water	Sea State		Weather Time	Temp (deg F)	Speed (kts)	Dir	(mi)	Cover (%)	(in)		Mammal Obs	
					111116		(kts)	Ait (it)	(sq mi)	water			Time	(ueg i)	(KLS)			(70)			Obs	
1	3/9/2017	fliaht	data s	heet no	t comple	ted fo		. 2017	(54 111)													
2	3/17/2017	, ,	1505	1550	1513		85	500	15	<25	0	0	1415	18.5	6.8	ENE	100+	0	0	TP	CISPRI PSO	No wildlife observed
_	3/20/2017		1010	1120	1028	-	85	500		<25	0	0	1135	26.4		NNW	100+	5			CISPRI PSO	No wildlife observed
4	3/22/2017	IBR	1305	1400	1311	Nik	85	500	20	25-50	0	0	1413	31.3	2.5	ESE	100+	0	0	Joe	CISPRI PSO	No wildlife observed. Approx. 20%
																						open water around leak site. Slight
																						swell seen under ice near leak per
																						WC.
5	3/31/2017	IBR	1445	1538	1437	Nik	85	350	see GPS	25-50	2	<1	1430	31.3	15.2	ENE	50+	100	0	Joe	CISPRI PSO	1 gull and 1 raven seen by PSO and
																						Pilot in survey area.
6	4/5/2017	_	1315	1410	1303	_	60-70		see GPS		2		1215	35.2		ENE	50+	100			CISPRI PSO	No wildlife observed
7	4/7/2017	_	1505	1605	1515		60		see GPS	99			1617	37.2		NNE	100+	50				One flying gull in survey area.
8	4/12/2017	IBR	1225	1320		Nik	78	380	see GPS	99	0	0	1145	39.7	6.1	WNW	100+	0	0	TP	CISPRI PSO	No wildlife observed
					narra-																	
0	4/19/2017	IDD	1106	1254	tive 1120	Nik	72	350	25	99	2	1	0.44444	39	4	N	100+	0	0	EH	CISPRI PSO	1 Herring Gull flying N; 2 Mew Gulls
9	4/19/2017	IDK	1100	1254	1120	INIK	12	330	25	99	2	1	0.44444	39	4	l in	100+	0	U	ЕП	CISPRI PSU	flying S; 1 Leach's Storm Petrel W;
																						10 Glaucous-winged Gulls flying
																						north
10	4/21/2017	IBR	1230	1400	1352	Nik	77	450	20	100	1	1	1135	46	4.5	ENE	100+	30	0	TC	CISPRI PSO	2 Glaucous-winged Gulls flying S to
	.,,										_	_							_			N thru middle; 3 Mew Gulls sitting
																						between A and C platform first
																						three circles, then flew away; 100
																						Geese flying N to S on the West
																						edge of area, about 1,000 feet; 3
																						Glaucous-winged gulls flying next to
	. /2.5 /2.5.=									400												shore by Helipad as we landed.
11	4/26/2017	IBR	1134	1234	1142	Nik	80	462	see GPS	100	2	<1	0.4875	41.9	4.4	NW	100+	90	0	unk	CISPRI PSO	1 gull flying near dock; 1 gull
																						perched on gravel island; 2 large
																						shorebirds (?) flushed from floating
																						debris; 1 raven flying past. Possibly additional unidentified birds seen
																						by pilots.
12	4/28/2017	IBR	1145	1245	1345	Nik	88	460	see GPS	100	1	negl.	1403	43.2	4.2	ENE	75	60	0	unk	CISPRI PSO	2 gulls, flock of 20 shorebirds, 2
12	-1/20/2017	libit	1145	1243	1545	IVIK	00	400	300 01 3	100	_	negi.	1403	43.2	7.2		,,,	00	U	unk	CISI III I SO	possible WWSC, 1 possible ARTE,
																						and 1 Bald Eagle.
13	5/1/2017	IBR	1530	1630	1600	Nik	72	330	see GPS	100	2-3	1	1430	45.3	17.3	E	50-	100	sprinkles	Chris	CISPRI PSO	Less gravel exposed. 5 unidentified
	, , ==-										-				-		75					gulls seen flying.

Cook Inlet Operations - Protected Species Observer Effort Log

Project ID:

PSO Milasp

Name:

Protected Species Observer

Initial: PSO

Vessel Name:

Hilcorp Helo

Protected Species Observer


PSO

Effort Log Page #:

MMO-009

	Observerel		Start o	of watch			End of	watch						
Date MM/DD/YYYY	Observers' Initials	Time	Latitude	Longitude	Depth (m)	Time	Latitude	Longitude	Depth (m)	Wind direction	Beaufort sea state	Swell (m)	Visibility (km)	Glare severity
oulor	PSO	1300	N-60°	W. 157°	A4 300,	1400	N. 60°	W. 151°	300-	8.7 Knot	φ	ø	onlimited	none
04/07/17	PSO	1500	N. 60° 44.330'	W. 151°	AH 523'	1356	N. 60° 47.943'	W. 151° 31. 893	A14 368		4	4	onlimited	none
04/12/2017	`PSO	1215	60°	151° 20.566W	ALT 380'	1310	60°	151° 31.676'W	ALT 380	WNW @6.1 KUT	\(\rightarrow \)	Ð	UNLIMIED	None
4/19/2017	PSO	1100	44:414, N	18.702'W	4LT 300	1216	60° 48.258' N	151° 35.557 w	4LT 300	N @4 KNT	\(\Phi \)	0	10 miles	10%
4/21/2017	PSO'.	1230	60°	151°	ALT 450	1340	46.469'N	151.° 30.545'W	ALT	NNE O 11 KUT	1 .	1	10mzces	5%
42417	PSO	1050	60° 46,9189 N.	151° 27.1875W	400,	1130	The same of the sa	151° 24.85754	Alt	55E C 1 Knt	Ø	φ	onlimited	None
W 28 17	PSO	1245	60° N 44.3530'	151' W	282'	1348	60° N 48.7129'	151° W	41+ 460	N. O LOKAT	Ø	ø	unlimited	None
V .														
a											¥			

Photograph Log



Photos were taken the vicinity of the leak with a view of Platform A. Flight circles are approximately 0.5 miles apart. The still water has been conducive to detecting flight or dive movements of wildlife.

ATTACHMENT B WATER QUALITY SAMPLING SUMMARY REPORT



Cook Inlet Methane Pipeline Leak Area

Water Quality and Air/Water Interface Monitoring

Weekly Report #7

Prepared by SLR International Corporation (SLR)

Report Date: 5-2-2017

1.0 OVERVIEW

The seventh water quality monitoring event was conducted from aboard the Offshore Service Vessel (OSV) Resolution during this reporting period using the approaches and methods described in the ADEC-approved plan (SLR 2017a). There was no air/water interface sampling this reporting period.

Safety of the vessel and crew was top priority during the monitoring activities. The quantity and location of sampling events were determined by site and weather conditions. The data presented herein is preliminary, subject to further review and verification by SLR International Corporation (SLR).

The revised location of the methane leak provided by Hilcorp prior to the first monitoring event on March 18 was used for the purposes of monitoring and reporting. This revised location and corresponding water depth is:

- Latitude 151°26'01.84"W, Longitude 60°46'35.68"N
- Easting1384137.82, Northing: 2478537.39
- Water Depth (MLLW) = 21.18 meters (69.51 feet)

This location is referred to as the Methane Release Point (MRP). Initial estimates of the leak rate ranged from 203 to 300 thousand cubic feet per day (MCFD). On March 13, Hilcorp reduced the pressure in the line and reported the gas flow rate from the leak was 193 to 215 MCFD. On March 25, 2017, the leak rate was further reduced to 85 to 115 MCFD. On April 10, the flow rate was further reduced to a reported rate of 78 to 108 MCFD. On April 13, the leak was stopped by applying a temporary clamp over the hole in the gas line. The temporary clamp was removed on April 19 during the slack tide around mid-day to allow for the installation of the permanent clamp. This operation took several dives during slack water. During the installation of the permanent clamp there was intermittent gas leakage from the pipeline as it could only be partially tightened. The permanent clamp failed to stop all the leakage and the temporary clamp was re-installed on April 20. The temporary clamp stopped the gas leakage.



As discussed in Section 2.2 of this report, based on the preliminary data review completed to date, the dissolved oxygen (DO) concentrations measured during this event and the previous events did not violate the Alaska Water Quality Standards (AWQS) as established in Title 18 Alaska Administrative Code (AAC), Chapter 75 (18 AAC 70).

2.0 WATER QUALITY MONITORING

2.1 Activities Completed

Water quality monitoring and sampling was conducted on April 25, 2017 which was 5 days after the temporary clamp stopped leakage from the pipeline and one day prior to a spring tide on April 26. The April 25 monitoring event covered portions of an ebb and flood tide. The NOAA tide predictions at the nearby East Forelands area predicted a low tide at 11:27 with height of -0.61 meters above mean lower low water (MLLW) on April 25. At the MRP site, the tide changes about 50 minutes after NOAA tidal predictions for the East Forelands area, and drifts were planned accordingly. The field team consisted of one SLR and one Kinnetic Laboratories, Inc. (KLI) scientist. The field team members (samplers) were Alaska Department of Environmental Conservation (ADEC) qualified samplers, per 18 Alaska Administrative Code 75.

The data collection activities followed the Water Quality Cook Inlet Alaska Methane Pipeline Leak Water Quality Sampling Plan (WQ Plan), (SLR 2017a). The primary data collection method utilized a drifting instrumented buoy to obtain water quality parameters in the area of interest. The drifting buoy had multiple instruments suspended along a line at three depth intervals (2, 7 and 12.5 meters) as depicted on Figure 1. The primary instruments are listed below:

- SeaBird Electronics, SBE 19 plus V2 SeaCAT- conductivity, depth, temperature (CTD), with dissolved oxygen (DO), pH, and turbidity.
- Pro-Oceanus Mini Methane
- Pro-Oceanus Mini Carbon Dioxide
- PME MiniDOT
- Garmin WAAS differential global positioning system (mounted on buoy and used to track the buoy's position during a monitoring transect)

Reported instrument depths below the water surface (bws) are based on length of line from the bottom of the buoy to the instrument(s). The buoy drifted with the current so the instrument string maintained a near vertical position during deployment. This was verified by review of the depth reading obtained by the CTD, which was located at the end of the line. As with Weeks 4, 5, and 6, during Week 7 the buoy was tethered to the deck of the boat, allowing for periodic adjustment of the buoy's travel path throughout the drift to better intercept the MRP. This method of deployment raised the buoy 1 meter above the water surface, and thus reduced the depth of the instruments in the water column a similar amount. Monitoring depths for this reporting period were approximately 1, 6 and 11.5 meters bws. A summary of the parameters measured by each instrument and frequency is provided in Attachment A, Table A-1.

During event 7, the site conditions impacted the activities completed as well as the collection of data, as noted below:



- No dive crew or buoys were near the MRP, therefore drifts could proceed without danger of entanglement in buoy lines.
- No sea ice was encountered during the seventh event. The seas were relatively flat.
- Air temperatures varied between 4 and 8 °C with water temperatures typically about 0.9 to 1.3 °C.
- The MiniCH4 and MiniCO2 sensors at both depths were mounted with the membrane facing the water's surface as precautionary measure to prevent gas bubbles from the MRP becoming trapped within the enclosure surrounding the membrane. Prior to the Week 4 event, these sensors had been mounted with the membrane facing toward the seafloor. Starting on Week 5, the deeper (12 meter) sensor was mounted upward as well.
- The deep and middle depth sensors where soaked in a container of seawater prior to and between drifts to keep them closer to ambient conditions when deployed. The sea water was collected from Cook Inlet prior the first drift near the project site. This technique was used the previous week as well, and appeared to reduce the sensors equilibrium time following deployment.

Three water quality buoy drifts (monitoring transects) were conducted through the area surrounding the MRP on April 25 at differing tidal stages. The duration of each water quality buoy drift varied from approximately 17 to 45 minutes. The average drift speed varied between 8.8 and 9.7 kilometers per hour. Table A-2 in Attachment A provides a summary of the buoy deployments. Attachment A. Figure A-2g illustrates the path of the three buoy drifts. During all three drifts the temporary clamp was installed on the natural gas line and no gas was observed bubbling around the MRP.

Drift #1 occurred during the ebb tide. The buoy was deployed approximately 1,700 meters up current of the MRP and was allowed to drift down current at total of 5978 meters, with periodic adjustment using the vessel to guide it safely past the MRP. The buoy passed within 29.6 meters of the MRP about 13 minutes into the drift.

Drift #2 occurred during the flood tide. The drift began approximately 1,500 meters up current of the MRP. Wind interfered with projected drift pattern and the drift was terminated immediately after passing the MRP due the poor trajectory. At its closest point, the buoy was 202 meters southwest of the MRP. At that point it was decided to reposition the buoy for another attempt at passing closer to the MRP.

Drift #3 occurred during the flood tide. The drift began approximately 700 meters up current of the MRP, and the buoy drifted down current a total of 4007 meters. The buoy passed within 27.9 meters of the MRP about 6.5 minutes into the drift.

No CTD casts were performed during Week 7.

No water samples for laboratory analysis were collected during Week 7.

A photograph log documenting the data collection methods and site conditions during Week 7 is included in Attachment A.



2.2 Summary of Results

2.2.1 Buoy Transects-Week 7

Data plots for the primary parameters of interest (DO, CH₄ and CO₂) for the water quality buoy Drifts #1 and #3 completed on April 25 are provided on Figures A-10.1 and A-10.2 in Attachment A. Drift #2 was terminated when it became evident the buoy would did not come close to the MRP. The data obtained during Drift #2 was not considered relevant for analysis or reporting purposes, and is not discussed.

- Dissolved Oxygen- The lowest DO value recorded after the sensor had time to stabilize and passed the MRP was 11.55 mg/L during Drift #1 and 11.53 mg/L during Drift #3. These lowest values were both recorded on the deepest DO sensor deployed at 11.5 meters on the CTD. There was no significant drop in DO concentrations recorded by the sensors as they passed the MRP, and measurements from each sensor were relatively stable throughout the drift (Attachment A, Figures A-10.1a and A-10.2a).
- Dissolved Methane: The maximum CH₄ concentration recorded was 0.107 and 0.096 mg/L during Drifts #1 and #3, respectively. These values were recorded on the sensor deployed at 6 meters. The sensor at 11.5 meters recorded values about 0.05 to 0.6 mg/L less than the sensor at 6 meters which has been a typical pattern observed during the monitoring events. The recorded CH₄ concentrations did not show a noticeable (sharp) increase as the sensors passed the MRP, and were relatively stable and consistent throughout the two drifts (Attachment A, Figure A-10.2b and A-10.2b). Overall, the recorded CH₄ concentrations were in the lower range of concentrations measured during the project, and similar to the previous four weeks (March 29-April 25 events).
- Dissolved Carbon Dioxide CO₂ concentrations recorded during Drifts #1 and #2 did not show any sharp upward fluctuation as the buoy passed the MRP (Figure A-10.1c and Figure A-10.2c in Attachment A). The recorded concentrations varied the most during the initial 5 to 10 minutes of each drift and prior to passing the MRP, presumably as the instrument equilibrated with the water conditions. The measured CO₂ concentrations were typically between 0.9 and 1.2 mg/L, which is consistent with the values recorded each week during the project.

As during previous weeks, the lowest DO concentration measured during both drifts was well above the most stringent regulatory limit for DO in marine waters established in 18 AAC 70. The 18 AAC 70 Alaska Water Quality Standards for marine waters state the surface DO concentration in coastal waters may not be less than 6.0 mg/L for a depth of one meter except when natural conditions cause this value to be depressed. DO may not be reduced below 4 mg/L at any point beneath the surface. DO concentrations in estuaries and tidal tributaries may not be less than 5.0 mg/L except where natural conditions cause this value to be depressed.



2.2.2 Laboratory Results

There were no new laboratory sample results received for dissolved CH₄ and CO₂ this reporting period. All results for samples collected to date have been previously reported. The next water sampling event is planned for May 2.

2.3 Activities Planned for the Next Sampling Event

The next water quality sampling event is planned for May 2, 2017. Planned activities include:

- Collecting discrete water samples at similar locations to the sampling performed to-date for the project.
- Conducting deployments of the water quality buoy at varied tidal conditions, with deployments under flowing conditions.

These planned activities may need to be modified due to site conditions and logistics. The water sampling is considered a higher priority than the buoy drifts. This is the final planned water quality monitoring event.

3.0 AIR/WATER INTERFACE MONITORING

3.1 Activities Completed

No air/water interface monitoring occurred during this reporting period.

3.2 Preliminary Summary of Results

No air/water interface monitoring occurred during this reporting period.

3.3 Activities Planned for the Next Sampling Event

The next air / water interface sampling event is planned for May 2, 2017. Planned activities include conducting deployments of the Air / Water Interface buoy in the vicinity of the MRP. These planned activities may need to be modified due to site conditions and logistics. This is the final planned air/water interface monitoring event.

REFERENCES

SLR International Corporation (SLR). 2017a Water Quality Sampling Plan. Cook Inlet Alaska Methane Pipeline Leak, March 2017.

SLR. 2017b. Air/Interface Sampling Plan. Cook Inlet Alaska Methane Pipeline Leak, March 2017



ATTACHMENT A:

PHOTOGRAPH LOG:

Water Quality and Air/Water Interface Photograph Log (April 25, 2017)

TABLES:

Table A-1: Water Quality Buoy Instrumentation Summary, April 25, 2017

Table A-2: Summary of Water Quality Buoy Drifts

FIGURES:

Figure A-1: Water Quality Monitoring Buoy Schematic (March 23-April 25, 2017) Figure A-2e: Water Quality Monitoring Week 6 (April 25, 2017), Buoy Drift Tracks

Week 5 Data Plots:

Figure A-10.1a: Buoy Drift #1, April 25, 2017, Dissolved Oxygen


Figure A-10.1b: Buoy Drift #1, April 25, 2017, Dissolved Methane

Figure A-10.1c: Buoy Drift #1, April 25, 2107, Dissolved Carbon Dioxide

Figure A-10.2a: Buoy Drift #3, April 25, 2017, Dissolved Oxygen

Figure A-10.2b: Buoy Drift #3, April 25, 2017, Dissolved Methane

Figure A-10.2c: Buoy Drift #3, April 25, 2017, Dissolved Carbon Dioxide





Typical conditions during Week 7. There was no sea ice and relatively flat seas. Buoy is seen here tied to the boat during Drift 1. Bubbles were not observed on the water surface near the MRP at any point during the day.

Date: 4/25/2017



Photo 2: CTD and mid-level sensors were stored in a container of seawater collected from Cook Inlet near the project site to keep them as close to insitu conditions as possible between drifts.

Date: 4/25/2017

SL	R [®]	

Cook Inlet Alaska Methane Pipeline Leak Water Quality Sampling Report: Week 7

SITE PHOTOGRAPHS Job No: 105.00874.17021



Photo 3:

View of the deck and stern on the Resolution during Drift 3. Buoy is attached to the side of the boat on right. Conditions remained ice-free with waves less than 1 foot. Winds were approximately 10 knots out of the North.

Date: 4/25/2017



Table A-1: Water Quality Instrumentation Buoy Summary

Instrument Name	Parameters Measured	Measurement Unit	Measurement Frequency	Frequency Reported, Plotted on Data Analysis Figures	Notes		
PME MiniDOT	Temperature Dissolved Oxygen	degrees Celsius (°C) milligrams per liter (mg/L)	Once per minute	Once per minute	Unable to record at higher frequencies		
Pro-Oceanus MiniCO2 (0-	Partial pressure of CO2 in detector	Parts per million by volume (ppmv)	Once per 4 seconds	Once per 4 seconds	Note this is measured as a gaseous phase concentration, which is then converted to the		
1000ppm)	Detector total pressure	millibars			surrounding aqueous		
	Detector temperature	degrees Celsius (°C)			concentrations.		
Pro-Oceanus MiniCH4 (two instruments utilized, with	Partial pressure of CH4 in detector	Volume ratio (%)	Once per 4 seconds	Once per 4 seconds	Note this is measured as a gaseous phase concentratio which is then converted to the		
differing ranges 0-	Detector total pressure	millibars			surrounding aqueous		
1% and 0-100%)	Detector temperature	degrees Celsius			concentrations.		
	Depth	meters (M)					
	Pressure	decibar (dm)					
	Conductivity	Siemens per meter (S/m)					
	Temperature	degrees Celsius (°C)					
Seabird SBE 19plus V3 SeaCat	рН	Negative of the base 10 logarithm of the molar concentration of hydrogen	1 per 1/4 second	Once per 4 seconds	Collected data is average to 4 second reporting frequency		
	Optical backscatter (OBS)	Nephelometric Turbidity Units (NTU)					
	Dissolved Oxygen	milligrams per liter (mg/L)					
Garmin WAAS	Position	Latitude and longitude	Once per 2 seconds	Once per 2 seconds			

Table A-2: Summary of Water Quality Buoy Drifts

Buoy Type	Instrument(s) Depth (m)	Drift Name	General Tide Description	Proximity to Spring or Neap Tide ¹	Daily Tidal Range (High- Low) (m) ¹	Date	Release Location	Retrieval Location	Start of Data Collection (hr:min: sec) ²	End of Data Collection ²	Duration of Data Collection ²	Total Drift Distance (m) ²	Average Drift Velocity (km/hr) ²	Minimum Distance to MRP (m)	Drift Elapsed Time at Minimum Distance to MRP (hh:mm:ss)	Wind (knots & direction)	Wave Height (m)	Comments	Estimated flow from leak (MCFD)
Water Quality	Surface 7 Mid 7 Deep 12.5	D01-031817	Ebb		4.75	3/18/2017	60 46.622 N 151 25.718 W		14:52:20	15:09:55	0:17:35	1766	6.1	185.9	0:01:55	calm	0	CO2 sensor at 12.5 m unintentionally shut off, no data	
Water Quality	Surface 2 Mid 7 Deep 12.5	D01-031917	Flood	2 days before	3.84	3/19/2017		60 47.2 N 151 25.112 W	8:15:45	8:45:55	0:30:10	1930	3.8	44.9	0:05:10	15, SSW	0		193-295
Water Quality	Surface 2 Mid 7 Deep 12.5	D02-031917	Flood	neap tide event	3.64	3/19/2017	60 46.35 N 151 25.878 W	60 46.921 N 151 25.878 W	9:09:40	9:36:55	0:27:15	901	2.0	165.8	0:14:40	15, SSW	0	SeaBird DO sensor stopped recording after 5 minutes, potential icing	193-295
Water Quality	Surface 2 Mid 7 Deep 12.5	D03-031917	Flood/Slack/ Ebb			3/19/2017		151 23.097 W	9:58:00	11:57:30	1:59:30	3684	1.9	9.4	1:05:45	15, SSW	0.2		
Water Quality	Surface 2 Mid 7 Deep 12.5	D01-032317	Flood		3.08	3/23/2017	60 46.565 N 151 25.995 W		12:09:50	12:29:30	0:19:40	1675	5.1	71.2	0:00:05	0.4 SSW	0	SeaBird DO sensor clogged with ice, no 12.5 meter DO data	
Water Quality	Surface 2 Mid 7 Deep 12.5	D02-032317	Flood	3 days after	3.06	3/23/2017		60 47.755 N 151 26.248 W	13:10:40	13:54:55	0:44:15	3521	4.8	3.9	0:05:15	Calm	0	SeaBird DO sensor clogged with ice, no 12.5 meter DO data]
Water Quality	Surface 2 Mid 7 Deep 12.5	D03-032317	Flood/Slack/ Ebb	neap tide event		3/23/2017	60 46.781 N 151 25.884 W	60 46.537 N 151 26.248 W	15:29:55	16:24:30	0:54:35	675	0.36 (flood Tide) / 1.44 (Ebb Tide)	165.5	0:50:35	Calm	0		193-295
Water Quality	Surface 2 Mid 7 Deep 12.5	D04-032317	Ebb		4.33	3/23/2017	60 46.695 N 151 25.870 W	60 45.403 N 151 27.936 W	16:31:35	17:18:55	0:47:20	3037	3.9	2.6	0:04:45	Calm	0		
Water Quality	Surface 2 Mid 7 Deep 12.5	D01-032917	Ebb	1 day after	8.35	3/29/2017	60 46.725 N 151 25.624 W	60 44.322 N 151 29.507 W	11:07:24	11:45:36	0:38:12	5193	8.2	145.7	0:02:28	11, SW	0	Water pump for SeaBrid DO sensor clogged, no 12.5 m DO data	
Water Quality	Surface 2 Mid 7 Deep 12.5	D02-032917	Flood	spring tide event	7.86	3/29/2017	60 46.216 N 151 26.734 W	60 49.189 N 151 21.302 W	15:54:32	16:46:56	0:52:24	6962	8.0	142.7	0:05:32	Calm	0	Water pump for SeaBrid DO sensor clogged, no 12.5 m DO data	85-115
Water Quality	Surface 0.8 Mid 5.8 Deep 11.3	D01-040517	Flood	1 day after	3.57	4/5/2017	60 46.618 N 151 26.228 W	60 46.654 N 151 25.531 W	13:26:48	13:48:08	0:21:20	793	2.5	67.8	0:08:00	5-10, SSW	0.5		
Water Quality	Surface 0.8 Mid 5.8 Deep 11.3	D01-04057	Flood/Slack/ Ebb	neap tide event		4/5/2017	60 46.546 N 151 26.247 W	60 46.361 N 151 26.350 W	13:55:32	14:52:40	0:57:08	1094	0.72 (flood Tide) / 1.08 (Ebb Tide)	10.4	0:18:28	5-10, SSW	0.5		85-115
Water Quality	Surface 1.5 Mid 6.5 Deep 12	D01-041217	Ebb	1 day after	7.29	4/12/2017	60 47.025 N 151 25.319 W		11:21:08	12:09:20	0:48:12	6367	7.9	61.1	0:09:12	Calm	0		
Water Quality	Surface 1.5 Mid 6.5 Deep 12	D02-041217	Flood	spring tide event	6.98	4/12/2017	60 46.071 N 151 25.526 W	60 47.572 N 151 25.366 W	15:31:36	15:57:32	0:25:56	3614	7.4	222.9	0:07:32	Calm	0		78-108
Water Quality	Surface 1.5 Mid 6.5 Deep 12	D01-041917	Flood	neap tide	2.56	4/19/2017	60 46.039 N 151 26.973 W		9:32:48	11:18:36	1:45:48	5427	3.1	32.1	0:20:44	5, SSW	0.2	Temporay clamp was installed on pipeline leak on April 13, and inplace during this drift.	0
Water Quality	Surface 1.5 Mid 6.5 Deep 12	D02-041917	Ebb	. пеар ше	3.54	4/19/2017	60 46.944 N 151 25.555 W	60 45.000 N 151 28.091 W	13:05:44	14:16:16	1:10:32	4766	4.2	18.5	0:18:16	Calm	0.2	Temporary clamp was removed during this drift. Bubbling observed on water surface near MRP.	slight
Water Quality	Surface 1 Mid 6 Deep 11.5	D01-042517	Ebb		7.01	4/25/2017	60 45.15 N 151 25.205 W	60 44.932 N 151 29.030 W	10:07:36	10:56:36	0:45:00	5978	9.7	29.6	0:12:48	5-10	0.3	Temporay clamp was re-installed on April 20 and in place during this event. No bubbling observed.	
Water Quality	Surface 1 Mid 6 Deep 11.5	D02-042517	Flood	1 day before spring	7.59	4/25/2017		60 46.754 N 151 26.097 W	13:08:12	13:24:56	0:16:44	1727	8.6	202.3	0:16:44	5-10	0.3	Drift terminated due to poor trajectory (missed MRP).	0
Water Quality	Surface 1 Mid 6 Deep 11.5	D03-042517	Flood		7.59	4/25/2017	60 46.267 N 151 26.193 W	60 48.011 N 151 24.182 W	13:41:00	14:18:28	0:37:28	4007	8.8	27.9	0:06:24	10	0.3		


Abbreviations meters MCFD thousand cubic feet per day MRP Methane Release Point

Notes:

1 - Tidal information is from NOAA Tide Predictions for East Foreland. StationId:TWC1989


2-These times and corresponding statistics correspond to when the buoy instrument sensors reached deployment depth based on the CTD depth reading (12.5 meters) and when the instruments began to be retrieved at the end of the drift. This time interval corresponds to the time interval plotted on the figures.


FIGURE 1: WATER QUALITY MONITORING BUOY SCHEMATIC (MARCH 23, 29 and APRIL 5, 12, 19, 25, 2017)





S/N 37-415-20


datalogger:

















ADDITIONAL SAFETY DOCUMENTATION

DAILY JOB REPORT	to	Report No.	8
Directions: Note problems encountered, RFI's, verbal communications with	Peak Job No.	23054 Date	4/25/2017
Client's representative, change order work performed.	Job Name	HSE support for water samp	ling for Gas
Note any important events		Pipeline Leak	
Send a copy via fax to Nikiski office by 900 am.			
Work By PEAK:	Subs	Trade	PEAK
The work performed by 1 PEAK employee (Safety Professional I) was to provide HSE	No. of Men		No. of Men
support to the personnel obtaining water samples for the Hilcorp Pipeline Gas	1	SLR	
Leak. HSE support included: JSA, pre-job safety meeting, permit to work,	1	Kinnetic Lab	
continuous monitoring of three 4-gas meters and continuous safety support.		Peak HSE	1
Work by Subcontractors:			
Work performed by 2 subcontractors, was that of water sampling by 1			
SLR employee and 1 Kinetic Lab employees.			
Safety Topic/Injury's			
JSA and permit to work were completed for this job. Copy of JSA/permit to work		TOTAL	
is attached with this daily job report.		Equipment	
	3	4-gas meters (Hilcorp)	
Comments:			
Time line of events for this job are attached in a word document to this daily			
job report.			
Safety Professional	*******		
Supervisor			
Signature	·		

The follow is a list of events that took place for the Hilcorp pipeline gas leak air water interface sampling and acoustic testing on Sunday 4-25-2017:

- 0800 JSA and pre-job safety meeting completed
- 0815 Depart Port aboard the Resolution owned and operated by OMSI
- **0830** Weather noted: Overcast, wind at 5 knots, 1 foot seas and temperature at 40^* F.
- 0900— Three 4-gas meters were taped to wooden mop handles and taped to the railings of the vessel. The height of all the gas meters ranged between 5'6" and 6'0". One was placed at the bow, one was placed towards the front deck on the portside of the vessel and one was placed mid-deck on the starboard side of the vessel. The monitors were turned on at this time.
- **1010** First water sample buoy with 0% LEL on gas meters. (side of vessel)
- 1310 Second water sample buoy with 0% LEL on gas meters. (side of boat)
- **1430** Monitors off and headed back to port.
- **1450** Arrived to port and close out of Permit to Work.

There were no injuries/incidents and safety was a focus for all personnel performing today's tasks. Proper use of safety toe boots, gloves and life vests were noted throughout all tasks.



Permit to Work (PTW) / Job Safety Analysis (JSA)

	1 (11111	t to Work (1 1777) 300 Salety / 1	11017313 (3371)	Safety Professional							
	ISA's should be son	sidered prior to any work. JSA's are mandatory	y for that require the use of	Area con	troller:						
		mit to Work system.	y for that require the use of	Safety: <u>I</u>	Hilcorp Safety Professional						
	Hilcorp Alaska's Per	mit to work system.		Construc	Hilcorp Safety Professional The Hilcorp Environmental Specific Rep:	ecialist	-				
DATE: 4-25	5-17	START TIME: 4:00 E	IND TIME: 2000	I	cy Muster Area: <u>De c/c</u> of *						
EACHTY. A	.10	LOCATION / APEA	Talat Mala	19-07-5-4-25-15- MES 19-5-5-	GENERAL SAFETY CONSIDE	RATIONS	مارة XX أ	N N/A			
PACILITY:	- 1 h-3	LOCATION/AREA: <u>Look</u> ; -ane pipeline Leav Sampling & water	-	Are Stand	dard Operating Procedures available and b	peing followed?					
DDOJECT DESCRI	V T S VV	rome pipeline rear		 Do perso 	onnel have proper tools/equipment for the						
PROJECT DESCRI	PHON: WATER	Sampling & WATER	CALL TO LET TONE	Are tools	/equipment in good condition/inspected?						
	CONFIN	ED SPACE ENTRY REQUIREMENTS:		製	planned escape route?						
				Are perso	onnel aware of the location of First Aid su	pplies?		_			
The operations tea	m and work team have	evaluated the confined space and agree that	none of the following	<u> </u>	emergency notification procedures been						
conditions exist an	id a Confined Space Ent	ry Permit is not required. Operations Lead o	r Permit Issuer Initials:		orp EH&S been notified 72 hrs. prior to Co			MICES			
					ersonnel trained/ certified to use equipme						
, ,		y type of hazardous atmosphere.			ersonnel donning appropriate PPE?	2					
, ,	•	otential to entrap or engulf an entrant. y other serious safety or health hazard.		 	project create a hazard to others in the vie						
s) The spa	ice does not contain an	y Other Serious safety of Health Hazards	•		rsonnel understand correct incident/spill						
				Do all pe	isolitiei diderstaria correct inciacing spin	reporting.					
Additional Pern	nits Required: 🗌	Hot Work Confined Space Entry	/ 🔲 Isolation of Hazard	lous Energy	Excavation & Trenching						
			AZARD-CONTROL INDEX (THIS	LIST IS NOT EXH	AUSTIVE)		gwidthichte.				
SLIPS/TRIPS/FALLS		PINCA POINTS/SHARP OBJECTS	ENERGIZED EQUIPMENT		ELECTRICAL SHOCK	LOCK-OUT/TAG-OUT CO	NOITIONS	3			
Clean surfaces (h	ousekeeping)	Proper guarding	Granding		Testing	Electrical isolation					
Barricade		Proper body placement	Proper body placement		Grounding	Pressure isolation					
Focus on path			☐ No loose clothing		tquipment shielding/condition	Energized equipment					
Use alternate rou	ute	FIRE/EXPLOSION	REPETITIVE MOTION		☐GFCI's	Fire/explosion isolation	n				
Relocate equipm		Permitting	Proper technique/tools		Examine electrical clearances		_				
Examine scaffold		Air testing/monitoring	Ask for assistance			HAZARDOUS CHEMICALS	i				
Examine handrai	l condition	Remove combustible/flam materials	☐Work/rest schedule		LIFTING/PULLING/PUSHING	Consult MSDS	41				
ı		Fire watch	PRESSURE		Utilize right tools for job	Label/store container	,				
FALLS FROM ELEVA		Fire extinguishers	Communication		Proper technique	Spill prevention consider					
Move work to gr		Additional PPE	Barricading		Smaller/lighter loads	Additional PPE (Goggi	as etc.)				
Ladder inspection			Shielding		Examine path	ATMOSPHERIC					
Proper ladder ma		HIGH NOISE LEVELS	Proper body placement		Use alternate route Work rest schedule	Respirators					
Additional PPE (F	-all Protection)	Relocate work Additional PPE (Hearing protection etc.)	☐ Block & bleed protocol		Lwork rest scriedule	Testing/monitoring					
13 , 20, 17					\~ C -						
WORK TEAM LEA	ADER (print): <u>Envi</u>	ronmental Sampler	Signa	ture: <u>الم</u>	ronmental Sampler						
, PERMIT APPROV	'ER (print): 'Safety	/ Professional	Signa	iture:	Safety Professional						
AREA CONTROLL	1/	el Captain		ature:	Vessel Captain						
Revalidation or	r Extension Time (4	Hour Max):	. Clo	se Out Signatu	re: Environmental Sampler		12->)			
Permit Approver	r (print):	Time:	Work leam Leader: Time: Time:								
Signature			Arc	ea Controller: _	Vessel Captain	Time:	17)	<u>U</u>			

Emergency Contact Info

HILCORP ALASKA. LLC: JOB SAFETY ANALYSIS (JSA)

JOB STEPS (Describe and pumber each step) 1 Travel to location cetrieval to redeployment of equipment and travel to port	POTENTIAL HAZARDS ASSOCIATED WITH EACH IOB STEP (Identify each hazard with a CAPITAL letter) A Heavy seas/wind - fall overbourn wind burn, items moving, falls cool temps - frost bite, skin gere irritation cold exposure Dangerous atmosphere - contact with increased CEL No	CORRECTIVE ACTION(S) (Identify responsible person with initials) Hand rails, floatation aderices pilot data, capt discretion, non-slip foot wear, store items D cold weather gear/protocol continuess monitoring L w/ 3 4-gas meters
	A Finch points, crushing, cuts	Idealify Dinch points
	A Falls overboard, strips B caught by moving falling overhead material, crush, struck-by	Flotation device, reep a path clear, the off communicate, eye of D sight on equipment notworking under items C communication, hard hats, safety toe boots, trained for use of crane

This JSA should be reviewed by everyone involved with the project. This JSA is not considered complete until everyone involved with the project signs below, along with any other contributing personnel. Should personnel need more space to complete the JSA, or if new hazards are presented due to changing conditions, an additional JSA form should be utilized and attached to these pages. Make notes on how the task can be performed in an even safer manner, and keep JSA's on file so that they may be referenced in the future should a similar project be conducted.

	Environmental Sampler	
INVOLVED PERSONNEL SIGNATURES:	Environmental Sampler	
	Safety Professional	